

8.1.2.1 Mitigation DIST OH Hardening - Covered Conductor ID WMP.455	8.1.2.10.1 Mitigation Avian Protection ID WMP.972	8.1.2.10.2 Mitigation Strategic Pole Replacement ID WMP.1189	8.1.2.11.1 Mitigation PSPS Sectionalizing Enhancements ID WMP.461	8.1.2.11.2 Mitigation Standby Power (Fixed Power Backup) ID WMP.468	8.1.2.2 Mitigation Strategic Undergrounding ID WMP.473	8.1.2.5.1 Mitigation DIST OH Hardening - Traditional Hardening ID WMP.475	8.1.2.5.2 Mitigation Transmission OH Hardening ID WMP.543	8.1.2.5.2. Mitigation Transmission OH Hardening - DUB ID WMP.545
8.1.2.7 Mitigation Microgrids ID WMP.462	8.1.2.8.1 Mitigation Advanced Protection ID WMP.463	8.1.2.8.2 Mitigation Early Fault Detection ID WMP.1195	8.1.2.8.3 Mitigation Distribution Communications Reliability Improvements (DCRI) ID WMP.549	8.1.3.1 Mitigation Distribution OH Detailed Inspections ID WMP.478	8.1.3.10 Mitigation Transmission 69kV tier 3 visual inspections ID WMP.555	8.1.3.11 Mitigation Substation Patrol Inspections ID WMP.492	8.1.3.2 Mitigation Transmisson OH Detailed Inspections ID WMP.479	8.1.3.3 Mitigation Distribution Infrared Inspections ID WMP.481
8.1.3.4 Mitigation Transmission Infrared Inspections ID WMP.482	8.1.3.5 Mitigation Distribution Woodpole Intrusive ID WMP.483	8.1.3.6 Mitigation Transmission Wood Pole Intrusive Inspections ID WMP.1190	8.1.3.7 Mitigation Distribution Drone Assessments ID WMP.552	8.1.3.8 Mitigation Distribution OH Patrol Inspections ID WMP.488	8.1.3.9 Mitigation Transmission OH Inspections (visual - helo patrol) ID WMP.489	8.1.4.3 Mitigation Capacitor Maintenance and Replacement (SCADA) ID WMP.453	8.1.4.4 Mitigation Expulsion Fuse Replacements ID WMP.459	8.1.4.5 Mitigation Hotline Clamps ID WMP.464
8.1.4.6 Mitigation Lightning Arrester Replacement ID WMP.550	8.1.6.1 Mitigation QA/QC of Transmission Inspections ID WMP.1191	8.1.6.2 Mitigation QA/QC Distribution Detailed ID WMP.491	8.1.6.3 Mitigation QA/QC Distribution Drone ID WMP.1192	8.1.6.4 Mitigation QA/QC Wood Pole Intrusive (Dist & Trans) ID WMP.1193	8.1.6.5 Mitigation QA/QC Substations ID WMP.1194	8.3.3.1 Mitigation Wireless Fault Indicators ID WMP.449		

Vegetation Management & Inspection

4.1.1	4.1.2	8.2.2.1	8.2.2.2	8.2.3	8.2.3.1	8.2.3.3	8.2.5
Mitigation Weather Station Maintenance and Calibration	Mitigation Air Quality Station Maintenance	Mitigation Detailed Inspections	Mitigation VM Off-Cycle Patrol (strike potential)	Mitigation Fuels Management Program	Mitigation Pole Clearing (brushing)	Mitigation Clearance (enhanced trim or remove)	Mitigation QA/QC Vegetation Management
ID WMP.1430	ID WMP.1431	ID WMP.494	ID WMP.508	ID WMP.497	ID WMP.512	ID WMP.501	ID WMP.505

<div>8.1.2.1</div> <div>Mitigation</div> <div>DIST OH Hardening - Covered Conductor</div> <div>WMP ID</div> <div>WMP.455</div> <div>Q3 Actual</div> <div>25.49</div> <div>QDR % Complete</div> <div>51%</div> <div>QDR Comments</div> <div>Approved target change in Petition to Amend Decision issued on July 11, 2025.</div>	<div>8.1.2.10.1</div> <div>Mitigation</div> <div>Avian Protection</div> <div>WMP ID</div> <div>WMP.972</div> <div>Q3 Actual</div> <div>508</div> <div>QDR % Complete</div> <div>254%</div> <div>QDR Comments</div> <div>-</div>	<div>8.1.2.10.2</div> <div>Mitigation</div> <div>Strategic Pole Replacement</div> <div>WMP ID</div> <div>WMP.1189</div> <div>Q3 Actual</div> <div>200</div> <div>QDR % Complete</div> <div>100%</div> <div>QDR Comments</div> <div>Approved target change in Petition to Amend Decision issued on July 11, 2025.</div>	<div>8.1.2.11.1</div> <div>Mitigation</div> <div>PSPS Sectionalizing Enhancements</div> <div>WMP ID</div> <div>WMP.461</div> <div>Q3 Actual</div> <div>4</div> <div>QDR % Complete</div> <div>40%</div> <div>QDR Comments</div> <div>-</div>	<div>8.1.2.11.2</div> <div>Mitigation</div> <div>Standby Power (Fixed Power Backup)</div> <div>WMP ID</div> <div>WMP.468</div> <div>Q3 Actual</div> <div>25</div> <div>QDR % Complete</div> <div>28%</div> <div>QDR Comments</div> <div>-</div>	<div>8.1.2.2</div> <div>Mitigation</div> <div>Strategic Undergrounding</div> <div>WMP ID</div> <div>WMP.473</div> <div>Q3 Actual</div> <div>44.08</div> <div>QDR % Complete</div> <div>157%</div> <div>QDR Comments</div> <div>Approved target change in Petition to Amend Decision issued on July 11, 2025.</div>	<div>8.1.2.5.1</div> <div>Mitigation</div> <div>DIST OH Hardening - Traditional Hardening</div> <div>WMP ID</div> <div>WMP.475</div> <div>Q3 Actual</div> <div>0.11</div> <div>QDR % Complete</div> <div>100%</div> <div>QDR Comments</div> <div>-</div>	<div>8.1.2.5.2</div> <div>Mitigation</div> <div>Transmission OH Hardening</div> <div>WMP ID</div> <div>WMP.543</div> <div>Q3 Actual</div> <div>0</div> <div>QDR % Complete</div> <div>0%</div> <div>QDR Comments</div> <div>Approved target change in Petition to Amend Decision issued on July 11, 2025.</div>
<div>8.1.2.5.2.</div> <div>Mitigation</div> <div>Transmission OH Hardening - DUB</div> <div>WMP ID</div> <div>WMP.545</div> <div>Q3 Actual</div> <div>0</div> <div>QDR % Complete</div> <div>0%</div> <div>QDR Comments</div> <div>-</div>	<div>8.1.2.7</div> <div>Mitigation</div> <div>Microgrids</div> <div>WMP ID</div> <div>WMP.462</div> <div>Q3 Actual</div> <div>0</div> <div>QDR % Complete</div> <div>(Blank)</div> <div>QDR Comments</div> <div>-</div>	<div>8.1.2.8.1</div> <div>Mitigation</div> <div>Advanced Protection</div> <div>WMP ID</div> <div>WMP.463</div> <div>Q3 Actual</div> <div>7</div> <div>QDR % Complete</div> <div>88%</div> <div>QDR Comments</div> <div>-</div>	<div>8.1.2.8.2</div> <div>Mitigation</div> <div>Early Fault Detection</div> <div>WMP ID</div> <div>WMP.1195</div> <div>Q3 Actual</div> <div>90</div> <div>QDR % Complete</div> <div>150%</div> <div>QDR Comments</div> <div>-</div>	<div>8.1.2.8.3</div> <div>Mitigation</div> <div>Distribution Communications Reliability Improvements (DCRI)</div> <div>WMP ID</div> <div>WMP.549</div> <div>Q3 Actual</div> <div>3</div> <div>QDR % Complete</div> <div>60%</div> <div>QDR Comments</div> <div>Approved target change in Petition to Amend Decision issued on July 11, 2025.</div>	<div>8.1.3.1</div> <div>Mitigation</div> <div>Distribution OH Detailed Inspections</div> <div>WMP ID</div> <div>WMP.478</div> <div>Q3 Actual</div> <div>17180</div> <div>QDR % Complete</div> <div>129%</div> <div>QDR Comments</div> <div>-</div>	<div>8.1.3.10</div> <div>Mitigation</div> <div>Transmission 69kV tier 3 visual inspections</div> <div>WMP ID</div> <div>WMP.555</div> <div>Q3 Actual</div> <div>1146</div> <div>QDR % Complete</div> <div>70%</div> <div>QDR Comments</div> <div>-</div>	<div>8.1.3.11</div> <div>Mitigation</div> <div>Substation Patrol Inspections</div> <div>WMP ID</div> <div>WMP.492</div> <div>Q3 Actual</div> <div>287</div> <div>QDR % Complete</div> <div>75%</div> <div>QDR Comments</div> <div>-</div>
<div>8.1.3.2</div> <div>Mitigation</div> <div>Transmission OH Detailed Inspections</div> <div>WMP ID</div> <div>WMP.479</div> <div>Q3 Actual</div> <div>1927</div> <div>QDR % Complete</div> <div>78%</div> <div>QDR Comments</div> <div>-</div>	<div>8.1.3.3</div> <div>Mitigation</div> <div>Distribution Infrared Inspections</div> <div>WMP ID</div> <div>WMP.481</div> <div>Q3 Actual</div> <div>211</div> <div>QDR % Complete</div> <div>70%</div> <div>QDR Comments</div> <div>-</div>	<div>8.1.3.4</div> <div>Mitigation</div> <div>Transmission Infrared Inspections</div> <div>WMP ID</div> <div>WMP.482</div> <div>Q3 Actual</div> <div>6976</div> <div>QDR % Complete</div> <div>95%</div> <div>QDR Comments</div> <div>-</div>	<div>8.1.3.5</div> <div>Mitigation</div> <div>Distribution Woodpole Intrusive</div> <div>WMP ID</div> <div>WMP.483</div> <div>Q3 Actual</div> <div>1228</div> <div>QDR % Complete</div> <div>357%</div> <div>QDR Comments</div> <div>-</div>	<div>8.1.3.6</div> <div>Mitigation</div> <div>Transmission Wood Pole Intrusive Inspections</div> <div>WMP ID</div> <div>WMP.1190</div> <div>Q3 Actual</div> <div>75</div> <div>QDR % Complete</div> <div>66%</div> <div>QDR Comments</div> <div>-</div>	<div>8.1.3.7</div> <div>Mitigation</div> <div>Distribution Drone Assessments</div> <div>WMP ID</div> <div>WMP.552</div> <div>Q3 Actual</div> <div>5260</div> <div>QDR % Complete</div> <div>39%</div> <div>QDR Comments</div> <div>-</div>	<div>8.1.3.8</div> <div>Mitigation</div> <div>Distribution OH Patrol Inspections</div> <div>WMP ID</div> <div>WMP.488</div> <div>Q3 Actual</div> <div>83769</div> <div>QDR % Complete</div> <div>97%</div> <div>QDR Comments</div> <div>-</div>	<div>8.1.3.9</div> <div>Mitigation</div> <div>Transmission OH Inspections (visual - helo patrol)</div> <div>WMP ID</div> <div>WMP.489</div> <div>Q3 Actual</div> <div>7263</div> <div>QDR % Complete</div> <div>96%</div> <div>QDR Comments</div> <div>-</div>
<div>8.1.4.3</div> <div>Mitigation</div> <div>Capacitor Maintenance and Replacement (SCADA)</div> <div>WMP ID</div> <div>WMP.453</div> <div>Q3 Actual</div> <div>0</div> <div>QDR % Complete</div> <div>(Blank)</div> <div>QDR Comments</div> <div>-</div>	<div>8.1.4.4</div> <div>Mitigation</div> <div>Expulsion Fuse Replacements</div> <div>WMP ID</div> <div>WMP.459</div> <div>Q3 Actual</div> <div>316</div> <div>QDR % Complete</div> <div>45%</div> <div>QDR Comments</div> <div>-</div>	<div>8.1.4.5</div> <div>Mitigation</div> <div>Hotline Clamps</div> <div>WMP ID</div> <div>WMP.464</div> <div>Q3 Actual</div> <div>107</div> <div>QDR % Complete</div> <div>11%</div> <div>QDR Comments</div> <div>-</div>	<div>8.1.4.6</div> <div>Mitigation</div> <div>Lightning Arrester Replacement</div> <div>WMP ID</div> <div>WMP.550</div> <div>Q3 Actual</div> <div>660</div> <div>QDR % Complete</div> <div>733%</div> <div>QDR Comments</div> <div>Approved target change in Petition to Amend Decision issued on July 11, 2025.</div>	<div>8.1.6.1</div> <div>Mitigation</div> <div>QA/QC of Transmission Inspections</div> <div>WMP ID</div> <div>WMP.1191</div> <div>Q3 Actual</div> <div>100</div> <div>QDR % Complete</div> <div>100%</div> <div>QDR Comments</div> <div>-</div>	<div>8.1.6.2</div> <div>Mitigation</div> <div>QA/QC Distribution Detailed</div> <div>WMP ID</div> <div>WMP.491</div> <div>Q3 Actual</div> <div>982</div> <div>QDR % Complete</div> <div>1488%</div> <div>QDR Comments</div> <div>-</div>	<div>8.1.6.3</div> <div>Mitigation</div> <div>QA/QC Distribution Drone</div> <div>WMP ID</div> <div>WMP.1192</div> <div>Q3 Actual</div> <div>5260</div> <div>QDR % Complete</div> <div>81%</div> <div>QDR Comments</div> <div>-</div>	<div>8.1.6.4</div> <div>Mitigation</div> <div>QA/QC Wood Pole Intrusive (Dist & Trans)</div> <div>WMP ID</div> <div>WMP.1193</div> <div>Q3 Actual</div> <div>1329</div> <div>QDR % Complete</div> <div>105%</div> <div>QDR Comments</div> <div>-</div>
<div>8.1.6.5</div> <div>Mitigation</div> <div>QA/QC Substations</div> <div>WMP ID</div> <div>WMP.1194</div> <div>Q3 Actual</div> <div>18</div> <div>QDR % Complete</div> <div>100%</div> <div>QDR Comments</div> <div>-</div>	<div>8.3.3.1</div> <div>Mitigation</div> <div>Wireless Fault Indicators</div> <div>WMP ID</div> <div>WMP.449</div> <div>Q3 Actual</div> <div>0</div> <div>QDR % Complete</div> <div>(Blank)</div> <div>QDR Comments</div> <div>-</div>						

8.2.2.1
Mitigation
Detailed Inspections

WMP ID
WMP.494
Q3 Actual
386418
QDR % Complete
80%
QDR Comments
-

8.2.2.2
Mitigation
VM Off-Cycle Patrol (strike
potential)

WMP ID
WMP.508
Q3 Actual
106
QDR % Complete
100%
QDR Comments
-

8.2.3
Mitigation
Fuels Management Program

WMP ID
WMP.497
Q3 Actual
447
QDR % Complete
89%
QDR Comments
-

4.1.1
Mitigation
Weather Station Maintenance
and Calibration

WMP ID
WMP.1430
Q3 Actual
216
QDR % Complete
100%
QDR Comments
-

8.2.3.1
Mitigation
Pole Clearing (brushing)

WMP ID
WMP.512
Q3 Actual
23865
QDR % Complete
72%
QDR Comments
-

8.2.3.3
Mitigation
Clearance (enhanced trim or
remove)

WMP ID
WMP.501
Q3 Actual
7127
QDR % Complete
64%
QDR Comments
-

8.2.5
Mitigation
QA/QC Vegetation
Management

WMP ID
WMP.505
Q3 Actual
0.29
QDR % Complete
29%
QDR Comments
-

4.1.2
Mitigation
Air Quality Station
Maintenance

WMP ID
WMP.1431
Q3 Actual
143
QDR % Complete
74%
QDR Comments
-